Service Records for your 2017 Chevrolet Cruze

Print

10 Service Records Found

Odometer Reading: 24,560 **Date 7/14/2026**

Source
Self-entered

Service Location
self

Service Information
Service Performed:
- Oil Change
- Filters

Total Cost
$35.00

Notes
Pennzoil Platinum Synthetic Dexos 5W30 & Purolator Boss L12222

Odometer Reading: 24,035 **Date 3/11/2026**

Source
Self-entered

Service Location
Twinsburg Goodyear

Service Information
Service #:
WO016305

Service Performed:
- Tires

Total Cost
$191.00

Notes
Intsall and balance 4x Yokohama Ascend LX P195/65R15

Odometer Reading: 23,114 **Date 6/29/2025**

Source
Self-entered

Service Location
self

Service Information
Service #:
1

Service Performed:
- Oil Change

Total Cost
$32.00

Notes
Pennzoil Platinum Synthetic Dexos 5W30 & Purolator L12222

Odometer Reading: 22,800 **Date 5/10/2025**

Source
Self-entered

Service Location
self

Service Information
Service #:
1

Service Performed:
- Other

Total Cost
$8.00

Notes
Flush brake system 1 quart DOT3, inspected caliper rubber boot covers, pads & rotors

Odometer Reading: 22,675 **Date 4/27/2025**

Source
Self-entered

Service Location
Self

Service Information
Service #:
0

Service Performed:
- Mileage-Specific Maintenance

Total Cost
$30.00

Notes
drain & refill autimatic transmission - 5.25 qts. Valvoline synthetic DexronXI

Odometer Reading: 22,165 **Date 1/1/2025**

Source
Self-entered

Service Location
self

Service Information
Service Performed:
- Battery
- Mileage-Specific Maintenance

Total Cost
$0.00

Notes

new ACDelco Gold Series battery 94RAGM & new ACDelco GM OEM A3202C Air Filter

Odometer Reading: 21,728 **Date 10/7/2024**

Source
Self-entered

Service Location
self

Service Information
Service Performed:
- Other

Total Cost
$0.00

Notes
cabin airfilter changed

Odometer Reading: 21,150 **Date 7/5/2024**

Source
Self-entered

Service Location
self

Service Information
Service Performed:
- Oil Change

Total Cost
$0.00

Notes
oil & filter (Pennzoil Platinum 5W30 & Purolator L12222)

Odometer Reading: 20,120 **Date 4/15/2024**

Source
Self-entered

Service Location
Self

Service Information
Service Performed:
- Emissions Control

Total Cost
$35.00

Notes
Installed new Oxygen Sensor Bank1-Sensor1 Bosch #16459

Odometer Reading: 19,200 **Date 7/15/2023**

Source
Self-entered

Service Location
owner

Service Information
Service Performed:
- Oil Change

Total Cost
$0.00

Notes
Pennzoil Platinum 5W30 & Purolator L12222

Print